



INDICATOR DIAGRAM, FIG. 1.
JOINT ABOVE ZERO EQUALS DEFLECTION OF JOINT AT X.
ETCHING BELOW ZERO SHEWS SLEEPER DEPRESSIONS.