

CONTENTS.

VOL. VIII.

ARTICLE.	PAGE.
— Officers for 1903—1904	iii.
I.—Presidential Address.	
By J. J. C. BRADFIELD, M.E., Assoc. M. Inst. C.E.	1
II.—Steel-Concrete Bridge Construction, Discussion on	21
III.—The Design of Riveted Joints in Girders.	
By W. H. WARREN, Wh. Sc., M. Inst. C.E., M. Am. Soc. C.E., Challis Professor of Engineering, University of Sydney..	36
IV.—The Use of Influence Lines in the Designing of Structures.	49
By R. W. HAWKEN, B.E., B.A.	51
V.—The Murray River Irrigation and Navigation.	
By R. T. MCKAY, Assist. Engineer, Dep. Public Works ...	101
VI.—Design of Retaining Walls, Pyrmont Bridge.	
By J. J. C. BRADFIELD, M.E., Assoc. M. Inst. C.E.	169
— Abstract of Proceedings	176
— List of Members	179

CORRIGENDA.—Page 3, line 1—for “painting” read “printing.”
Page 54, line 10—for “on” read “to.”
Page 54, line 17—put Σ in numerator.
Page 57, line 4—for “a” read “ α ”
Page 70, line 13—a space should be between “l” and “ \int ”
Page 133, plate 37—“The Murray River” should read “The Darling River.”
Page 160, line 8—for “240,000” read “146,000.”