


FINAL
PRESSURE
VACUUM
IN
INCHES
MERCURY



HEAT EFFICIENCY OF PERFECT

STEAM ENGINE BETWEEN TEMPERATURES
STEAM PRESSURE 100 LBS (Gauge)
T_{Cond} 70° F